

NUMARK CD2CD VERSION 1.11 BIOS UPDATE RELEASE NOTE

November, 2005: This BIOS update fixes a bug when using the "Copy Track" function that sometimes causes the final one or two seconds of some songs to be cut off when burned to a CD.

NUMARK CD2CD VERSION 1.11 BIOS UPDATE INSTRUCTIONS

1. Download the NUMARK.EPO file to a convenient location on your computer hard drive.
2. Burn the update file as a data file to a blank CD-R (or CD-RW) disc.
3. Insert this upgrade CD into the CD2CD Reader or Writer drive (either will work).
4. Using the track forward (>>) button, go to **5. System** and press the "**Start**" button.
5. Using the track forward (>>) button, go to **5.3 Upgrade System BIOS** and press the "**Start**" button. The system will begin installing the BIOS update and then reboot automatically when finished.
6. After the system reboots, the new firmware version will appear in the display.